



**Cardinal Environmental Consultants, Inc.**

2691 Dow Avenue, Suite C-2

Tustin, CA 92780

Phone: (714) 730-5931

Fax: (714) 730-1697

Date: April 5th, 2018

Owner/Client: Tustin Unified School District  
Maintenance and Operations  
1302 Service Road  
Tustin, California 92780

Attention: Mr. Dave Heckathorn

SUBJECT: **Results of AHERA Six Month Surveillance of Asbestos-Containing Materials – Winter, 2018**

Dear Dave Heckathorn:

During Winter 2018 Cardinal conducted the Six-Month Surveillance of Asbestos-Containing Materials, as required by the Asbestos Hazard Emergency Response Act (AHERA). Removals have been noted throughout the district, and some enclosures have also been noted. Our staff witnessed new improvements made in a couple of administration buildings. Carpet has been laid over enclosing some of the vinyl asbestos tiles.

The damaged report lists materials that are located in mechanical rooms and storage rooms not inhabited by students. No other damaged materials were found at the District. At a minimum, staff should continue to observe any damaged areas. Damage to the fire doors can cause a risk of exposure. It is highly recommended these be replaced with newer more suitable materials.

As you know, copies of individual school reports must be kept at each school site, which in turn must make them available to staff and parents upon request. As agreed, we have included a “thumb drive” with the AHERA documents.

Sincerely yours,

**CARDINAL ENVIRONMENTAL CONSULTANTS INC.,  
A California Corporation**

By:

**Ronald R. McDaniel**

California Certified Asbestos Consultant #01-2865

CDPH Certified Lead Inspector/Assessor and Project Monitor/Designer #3599

Registered Environmental Assessor

Certified Microbial Consultant by *American Indoor Air Quality Council*

***DAMAGE REPORT: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

---

**Tustin Unified School District  
DISTRICT ADMINISTRATION**

**TUSD  
17H**

**Inspection Date: 4/5/2018**

---

<b>Building</b>	Building C	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Boiler room and A/C room - Left door	<b>Condition</b>	<b>DAMAGED</b>	Damaged
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Remove and replace.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

---

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

***DAMAGE REPORT: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

**Tustin Unified School District  
NELSON ELEMENTARY SCHOOL**

**TUSD  
17V**

**Inspection Date: 4/5/2018**

<b>Building</b>	Building D	<b>Quantity</b>	5 LF 6"D	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>DAMAGED</b>	Deteriorating
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Repair or replace
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E	<b>Quantity</b>	6 LF 6"D	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>DAMAGED</b>	Torn; deteriorating, debris
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Repair or remove
		<b>Hazard Ranking</b>	4	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

***DAMAGE REPORT: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

**Tustin Unified School District  
TUSTIN MEMORIAL ELEMENTARY SCHOOL**

**TUSD  
17S**

**Inspection Date: 4/5/2018**

---

<b>Building</b>	C: Kindergarten	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial storage	<b>Condition</b>	<b>SIGNIFICANT DAMAGE</b>	Door is coming apart to reveal interior insulation
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	6	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Repair or Replace
		<b>Friable Non-Friable</b>	F	

---

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>ARROYO ELEMENTARY SCHOOL</b>			<b>17Q</b>	
<b>Building</b>	A, B, C, D, E, F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance Hazard Ranking</b>	LOW *	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A, B, C, D, E, F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; on selected windows
<b>Description</b>	Window putty	<b>Potential for Disturbance Hazard Ranking</b>	LOW *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A, B, C, D, E, F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	Cracked panel at room 12 and one broken at room 8
<b>Description</b>	Transite panels	<b>Potential for Disturbance Hazard Ranking</b>	MOD *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	40 SF	<b>Comments</b>
<b>Location</b>	Conference room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance Hazard Ranking</b>	LOW *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	165 SF	<b>Comments</b>
<b>Location</b>	Nurse's office	<b>Condition</b>	<b>REMOVED</b>	Removed July, 2004
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance Hazard Ranking</b>	N.A. *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	117 SF	<b>Comments</b>
<b>Location</b>	Supply room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance Hazard Ranking</b>	HIGH *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>ARROYO ELEMENTARY SCHOOL</b>		<b>17Q</b>		
<b>Building</b>	A: Administration	<b>Quantity</b>	154 SF	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage; partially enclosed by rug
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Exterior heater closet	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	350 SF	<b>Comments</b>
<b>Location</b>	Office and north end of classroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by new floor tile or removed
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C, D, E, F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	TSI	N.A.
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	West of ramp on south side of building E	<b>Condition</b>	<b>GOOD</b>	No significant damage; imbedded in asphalt
<b>Description</b>	Transite drain pipe	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**ARROYO ELEMENTARY SCHOOL**

**17Q**

<b>Building</b>	F	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Food service	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout except where noted	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	

**David Johnson Certified Site Surveillance  
Technician 17-5918**

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>BENSON ELEMENTARY (SYCAMORE)</b>			<b>17R</b>	
<b>Building</b>	A: Administration	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Above doors	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Transite panels	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Lounge above stovetop	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Transite panel	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Transite flue pipe	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	305 SF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Transite panels	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	9x9 Brown floor tile	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
		<b>Potential for Disturbance</b>	LOW	
<b>Description</b>	Fire door insulation	<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>BENSON ELEMENTARY (SYCAMORE)</b>			<b>17R</b>	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by ceiling tiles
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Classrooms	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial and storage rooms	<b>Condition</b>	<b>REMOVED</b>	Removed, 2006
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Classrooms	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Custodial room	<b>Condition</b>	<b>GOOD</b>	Light fixture lens missing; insulation exposed
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Replace missing lens
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Classrooms	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite flue pipes	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Storage room	<b>Condition</b>	<b>GOOD</b>	Loose and missing tiles
<b>Description</b>	12x12 Yellow floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Repair or replace
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>BENSON ELEMENTARY (SYCAMORE)</b>			<b>17R</b>	
<b>Building</b>	D: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by cove base
<b>Description</b>	Cove base mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Custodial and storage rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial and storage rooms	<b>Condition</b>	<b>GOOD</b>	Light fixture lenses are missing; insulation exposed
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Replace missing lenses
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>BENSON ELEMENTARY (SYCAMORE)</b>		<b>17R</b>		
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Drywall joint compound	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Multipurpose beams	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	4 EA	<b>Comments</b>
<b>Location</b>	Restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed, 2006
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Restroom portable	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2006; portable demolished
<b>Description</b>	Brown sheet vinyl	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**BENSON ELEMENTARY (SYCAMORE)**

**17R**

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Paper tape	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Patching compound	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

**David Johnson Certified Site Surveillance  
Technician 17-5918**

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>BESWICK ELEMENTARY SCHOOL</b>			<b>17U</b>	
<b>Building</b>	A - F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Building walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Exterior stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine Operations and Maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Copy and storeroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under non-ACM floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Hall and nurse	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under non-ACM floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Old furnace room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Old furnace room HWH	<b>Condition</b>	<b>GOOD</b>	Minor damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	4	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	2,800 SF	<b>Comments</b>
<b>Location</b>	Throughout except east end of teachers lounge	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>BESWICK ELEMENTARY SCHOOL</b>		<b>17U</b>		
<b>Building</b>	A: Administration	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Rooms A-1 to A-4	<b>Quantity</b>	4,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Rooms A-1 to A-4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Rooms C-1 to C-3	<b>Quantity</b>	2700 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>BESWICK ELEMENTARY SCHOOL</b>		<b>17U</b>		
<b>Building</b>	D: Rooms C-1 to C-3	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms E-1 to E-2	<b>Quantity</b>	1800 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms E-1 to E-2	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Rooms B-1 to B-4	<b>Quantity</b>	2700 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Rooms B-1 to B-4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Rooms D-1 to D-4	<b>Quantity</b>	2700 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>BESWICK ELEMENTARY SCHOOL</b>		<b>17U</b>		
<b>Building</b>	G: Rooms D-1 to D-4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Rooms F-1 to F-4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Rooms F1 to F-4	<b>Quantity</b>	160 SF	<b>Comments</b>
<b>Location</b>	F-1 Food service	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Rooms F1 to F-4	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Furnace room between F-2 and F-3	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Rooms F1 to F-4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Rooms F1 to F-4	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Throughout except F-1	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>BESWICK ELEMENTARY SCHOOL</b>		<b>17U</b>		
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Above ceiling panels	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Verify ACM; routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>GOOD</b>	Located on old ducts; minor damage
<b>Description</b>	Insulation paper	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Monitor damage
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	270 SF	<b>Comments</b>
<b>Location</b>	Stage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 12 X 12 VFT (verify removal)
<b>Description</b>	Orange sheet vinyl	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; above ceiling panels
<b>Description</b>	Drywall tape and mud	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

***AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

---

**Tustin Unified School District  
BESWICK ELEMENTARY SCHOOL**

**TUSD  
17U**

**Inspection Date: 4/5/2018**

---

**David Johnson Certified Site Surveillance  
Technician 17-5918**

---

***Inspector Signature***



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>			<b>17G</b>	
<b>Building</b>	A: Administration	<b>Quantity</b>	12 LF	<b>Comments</b>
<b>Location</b>	Above furnace and HWH	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite pipes	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	8 SF	<b>Comments</b>
<b>Location</b>	Coat closet	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Copy room and Nurse's office	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 Yellow floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	Partially removed Fall 1992
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Pipe fitting insulation behind walls and ceilings	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>			<b>17G</b>	
<b>Building</b>	A: Administration	<b>Quantity</b>	170 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: B1-B2 and Teachers lounge	<b>Quantity</b>	28 REG	<b>Comments</b>
<b>Location</b>	Classroom heat registers	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: B1-B2 and Teachers lounge	<b>Quantity</b>	2,200 SF	<b>Comments</b>
<b>Location</b>	Classrooms	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: B1-B2 and Teachers lounge	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: B1-B2 and Teachers lounge	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace rooms	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Duct tape and flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: B1-B2 and Teachers lounge	<b>Quantity</b>	250 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>		<b>17G</b>		
<b>Building</b>	C: C1-C3	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room C1	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: C1-C3	<b>Quantity</b>	256 SF	<b>Comments</b>
<b>Location</b>	Room C2	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 White floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: C1-C3	<b>Quantity</b>	644 SF	<b>Comments</b>
<b>Location</b>	Room C2	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: C1-C3	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Room C3	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Blue floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: C1-C3	<b>Quantity</b>	250 LF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by cove base; <1% ACM
<b>Description</b>	Cove base mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: C1-C3	<b>Quantity</b>	36 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>			<b>17G</b>	
<b>Building</b>	E: E1-E3	<b>Quantity</b>	28 REG	<b>Comments</b>
<b>Location</b>	Classroom heat registers	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: E1-E3	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Insulating duct tape	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: E1-E3	<b>Quantity</b>	250 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: F1-F3	<b>Quantity</b>	200 LF	<b>Comments</b>
<b>Location</b>	Above ceiling	<b>Condition</b>	<b>ENCLOSED</b>	Exposed ends encapsulated
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: F1-F3	<b>Quantity</b>	125 SF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Tank insulation and debris	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: F1-F3	<b>Quantity</b>	200 LF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**COLUMBUS TUSTIN MIDDLE SCHOOL**

**17G**

<b>Building</b>	F: F1-F3	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: G1-G4	<b>Quantity</b>	28 REG.	<b>Comments</b>
<b>Location</b>	Classroom heat registers	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: G1-G4	<b>Quantity</b>	12 LF	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Duct tape and flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: G1-G4	<b>Quantity</b>	250 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: H1-H3	<b>Quantity</b>	3 LF	<b>Comments</b>
<b>Location</b>	Heater closet	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Duct tape and flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: H1-H3	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room H1	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>		<b>17G</b>		
<b>Building</b>	H: H1-H3	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Room H2	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 Pink floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: H1-H3	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room H3	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: H1-H3	<b>Quantity</b>	192 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: I1-I4	<b>Quantity</b>	24 REG.	<b>Comments</b>
<b>Location</b>	Classroom heat registers	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	I: I1-I4	<b>Quantity</b>	3,300 SF	<b>Comments</b>
<b>Location</b>	Classrooms	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: I1-I4	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>			<b>17G</b>	
<b>Building</b>	I: I1-I4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: J1-J4	<b>Quantity</b>	28 REG.	<b>Comments</b>
<b>Location</b>	Classroom heat registers	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: J1-J4	<b>Quantity</b>	6 LF EA	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Insulating duct tape	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: J1-J4	<b>Quantity</b>	250 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: K1-K2	<b>Quantity</b>	12 LF	<b>Comments</b>
<b>Location</b>	Heater closet	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: K1-K2	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Kiln (east side of K2)	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>		<b>17G</b>		
<b>Building</b>	K: K1-K2	<b>Quantity</b>	2,200 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: K1-K2	<b>Quantity</b>	192 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	L: Library	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace room - east side	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Duct tape and flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	L: Library	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Library workroom	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 Yellow floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	L: Library	<b>Quantity</b>	25 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	27 SF	<b>Comments</b>
<b>Location</b>	Above windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>COLUMBUS TUSTIN MIDDLE SCHOOL</b>		<b>17G</b>		
<b>Building</b>	Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>ENCLOSED</b>	In attic and under ceiling tiles
<b>Description</b>	Drywall joint compound	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	16	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	3	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	364 SF	<b>Comments</b>
<b>Location</b>	Band room M5	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	24 SF	<b>Comments</b>
<b>Location</b>	Custodial closet	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	10,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District** **TUSD**  
**COLUMBUS TUSTIN MIDDLE SCHOOL** **17G** **Inspection Date: 4/5/2018**

<b>Building</b>	Multipurpose	<b>Quantity</b>	3 LF	<b>Comments</b>
<b>Location</b>	Heater room at north side of kitchen	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	8 LF	<b>Comments</b>
<b>Location</b>	Heater room at north side of kitchen	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Kitchen	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Kitchen furnace room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Kitchen, pantry, serving and auditorium	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 Brown floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Main room	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	-	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**COLUMBUS TUSTIN MIDDLE SCHOOL**

**17G**

<b>Building</b>	Multipurpose	<b>Quantity</b>	1,800 SF	<b>Comments</b>
<b>Location</b>	Staff restrooms and kitchen	<b>Condition</b>	<b>ENCLOSED</b>	Removed in restrooms; enclosed under ceiling tiles in kitchen
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	Routine operations and maintenance
		<b>Type</b>	SUR	
		<b>Friable Non-Friable</b>	NF	

---

<b>Building</b>	Multipurpose	<b>Quantity</b>	550 SF	<b>Comments</b>
<b>Location</b>	Stage	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	12x12 White floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace rooms	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Transite pipes	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace rooms	<b>Condition</b>	<b>REMOVED</b>	Removed Fall 1992
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	-	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	400	<b>Quantity</b>	20 LF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Pipe Insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	400	<b>Quantity</b>	2,800 SF	<b>Comments</b>
<b>Location</b>	Entries and workrooms	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	400	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	400	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room 405	<b>Condition</b>	<b>REMOVED</b>	Removed June 2006
<b>Description</b>	Transite lab counter	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	500	<b>Quantity</b>	20 LF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	500	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Entries and workrooms	<b>Condition</b>	<b>REMOVED</b>	Remmoved Summer 2012
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	500	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Rooms 502 and 512	<b>Condition</b>	<b>REMOVED</b>	Removed June 2006
<b>Description</b>	Transite lab counter	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	600	<b>Quantity</b>	15 LF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Pipe injsulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	600	<b>Quantity</b>	2,800 SF	<b>Comments</b>
<b>Location</b>	Entries and workrooms	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	600	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	600	<b>Quantity</b>	1	<b>Comments</b>
<b>Location</b>	Room 605	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite lab counter	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	700	<b>Quantity</b>	210 SF	<b>Comments</b>
<b>Location</b>	Boys' Coaches' Office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	700	<b>Quantity</b>	210 SF	<b>Comments</b>
<b>Location</b>	Girls' Coaches' Office	<b>Condition</b>	<b>GOOD</b>	Minor damage at door
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	700	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Locker rooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 1x1 ceiling tiles
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	700	<b>Quantity</b>	5 SF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Gaskets	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	700	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	Boiler plate detached from boiler
<b>Description</b>	Boiler insulation	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	4	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Monitor for damage
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	700	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by fiberglass and wrap
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	800	<b>Quantity</b>	20 EA	<b>Comments</b>
<b>Location</b>	Above Ceiling	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe Insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	800	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Art storage by kiln	<b>Condition</b>	<b>REMOVED</b>	Removed summer 1997
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	8 EA	<b>Comments</b>
<b>Location</b>	Boiler Room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe Insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	800	<b>Quantity</b>	4 SF	<b>Comments</b>
<b>Location</b>	Kitchen	<b>Condition</b>	<b>REMOVED</b>	Removed (new appliance in place)
<b>Description</b>	Oven insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	800	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Kitchen hall and office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 1x1 ceiling tile, one missing tile
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Kitchen office	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Grey floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	30 SF	<b>Comments</b>
<b>Location</b>	Kitchen restroom	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Tan sheet vinyl	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	800	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Kitchen storeroom and hall	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Multipurpose	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 1x1 ceiling tile
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Multipurpose and 4 closets	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Multipurpose stage door	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	800	<b>Quantity</b>	1,124 SF	<b>Comments</b>
<b>Location</b>	Room 802 Music	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Room 802 Music	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 1x1 wall tile
<b>Description</b>	Wall tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	800	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room 803	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	800	<b>Quantity</b>	1,124 SF	<b>Comments</b>
<b>Location</b>	Room 803	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	980 SF	<b>Comments</b>
<b>Location</b>	Room 804	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	1,109 SF	<b>Comments</b>
<b>Location</b>	Room 805	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Olive floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	1,300 SF	<b>Comments</b>
<b>Location</b>	Room 808 Home Ec	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Tan floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	800	<b>Quantity</b>	1,109 SF	<b>Comments</b>
<b>Location</b>	Room 809	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet except at entry, torn
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	Administration	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Faculty women's restroom	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Brown sheet vinyl	<b>Potential for Disturbance</b>	N.A	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Health office restroom	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Brown sheet vinyl	<b>Potential for Disturbance</b>	N.A	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	55 SF	<b>Comments</b>
<b>Location</b>	Office workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	25 SF	<b>Comments</b>
<b>Location</b>	Thorman health office restroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Brown sheet vinyl	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	381 SF	<b>Comments</b>
<b>Location</b>	Exterior window panels	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof mansard	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2008
<b>Description</b>	Transite shingles	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**CURRIE MIDDLE SCHOOL**

**17C**

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof patches and penetrations	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2008
<b>Description</b>	Mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof walkways	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2008
<b>Description</b>	Black composition roofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

**David Johnson Certified Site Surveillance  
Technician 17-5918**

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>DISTRICT ADMINISTRATION</b>			<b>17H</b>	
<b>Building</b>	Building A	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Main entrance phone closet (NE)	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Brown floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Main entrance vault closet (SE)	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige and Grey floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Payroll room closet	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Red floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Print shop and offices	<b>Condition</b>	<b>GOOD</b>	No significant damage; one office enclosed by carpet
<b>Description</b>	12x12 Brown and Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	425 SF	<b>Comments</b>
<b>Location</b>	Print shop hall	<b>Condition</b>	<b>GOOD</b>	Minor damage
<b>Description</b>	12x12 Brown and Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Print shop health storage closet	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Brown floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>DISTRICT ADMINISTRATION</b>		<b>17H</b>		
<b>Building</b>	Building A	<b>Quantity</b>	1,800 SF	<b>Comments</b>
<b>Location</b>	Print shop paper storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	12x12 Brown and Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	45 SF	<b>Comments</b>
<b>Location</b>	Print shop woman's restroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by sheet vinyl or removed
<b>Description</b>	12x12 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Verify presence; routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	60 SF	<b>Comments</b>
<b>Location</b>	Roof access closet	<b>Condition</b>	<b>GOOD</b>	No significant damage; near interior restrooms
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	16,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Wall plaster	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A	<b>Quantity</b>	12,000 SF	<b>Comments</b>
<b>Location</b>	Throughout under carpet	<b>Condition</b>	<b>ENCLOSED</b>	200 SF exposed in three closets
<b>Description</b>	9x9 Beige and Grey floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**HERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**DISTRICT ADMINISTRATION**

**17H**

<b>Building</b>	Building C	<b>Quantity</b>	20 LF	<b>Comments</b>
<b>Location</b>	Boiler room and A/C room - Left door	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building C	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Boiler room and A/C room - Left door	<b>Condition</b>	<b>DAMAGED</b>	Damaged
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building C	<b>Quantity</b>	55 EA	<b>Comments</b>
<b>Location</b>	Boiler room and A/C room - Right door	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2012
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building C	<b>Quantity</b>	120 SF	<b>Comments</b>
<b>Location</b>	Exterior restrooms	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Brown floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building C	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Mechanical Room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite pipe	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**DISTRICT ADMINISTRATION**

**TUSD**  
**17H**

**Inspection Date: 4/5/2018**

<b>Building</b>	Building D	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Communication Room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2011
<b>Description</b>	Linoliumn Flooring	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine Operations And Maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2011
<b>Description</b>	Roof Mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine Operations And Maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2011
<b>Description</b>	Roof Mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine Operations And Maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
 Technician 17-5918

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>		<b>17M</b>		
<b>Building</b>	A: Rooms A1 to A6	<b>Quantity</b>	36,00 SF	<b>Comments</b>
<b>Location</b>	Classrooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Rooms A1 to A6	<b>Quantity</b>	10,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Rooms A1 to A6	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Rooms A1 to A6	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Nurse's office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet except in storage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>		<b>17M</b>	
<b>Building</b>	Administration	<b>Quantity</b>	800 SF
<b>Location</b>	Teachers lounge	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Enclosed by carpet
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	Administration	<b>Quantity</b>	400 SF
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage; some are metal
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	Administration	<b>Quantity</b>	287 SF
<b>Location</b>	Workroom and storage	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	3,600 SF
<b>Location</b>	Classrooms	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Enclosed by carpet
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	8,000 SF
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage; <1% ACM
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	500 SF
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	F
<b>Comments</b>			No significant damage; <1% ACM
<b>Recommended Response Action</b>			Routine operations and maintenance

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>		<b>17M</b>	
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	2 EA
<b>Location</b>	Food service	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	F
			<b>Comments</b>
			Enclosed inside doors
			<b>Recommended Response Action</b>
			Routine operations and maintenance
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	N.A.
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.
		<b>Hazard Ranking</b>	
		<b>Type</b>	TSI
		<b>Friable Non-Friable</b>	F
			<b>Comments</b>
			Removed
			<b>Recommended Response Action</b>
			N.A.
<b>Building</b>	B: Rooms B1 to B5	<b>Quantity</b>	500 SF
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
			<b>Comments</b>
			No significant damage
			<b>Recommended Response Action</b>
			Routine operations and maintenance
<b>Building</b>	C: Rooms C1 to C6	<b>Quantity</b>	3,600 SF
<b>Location</b>	Classrooms	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
			<b>Comments</b>
			Enclosed by carpet
			<b>Recommended Response Action</b>
			Routine operations and maintenance
<b>Building</b>	C: Rooms C1 to C6	<b>Quantity</b>	8,000 SF
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	NF
			<b>Comments</b>
			No significant damage; <1% ACM
			<b>Recommended Response Action</b>
			Routine operations and maintenance
<b>Building</b>	C: Rooms C1 to C6	<b>Quantity</b>	N.A.
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.
		<b>Hazard Ranking</b>	
		<b>Type</b>	TSI
		<b>Friable Non-Friable</b>	F
			<b>Comments</b>
			Removed
			<b>Recommended Response Action</b>
			N.A.

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>			<b>17M</b>	
<b>Building</b>	C: Rooms C1 to C6	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Rooms D1 to D4	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Rooms D1 to D4	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Rooms D1 to D4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D: Rooms D1 to D4	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms D1 to D4	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Classrooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>		<b>17M</b>		
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Classrooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Rooms E1 to E4	<b>Quantity</b>	578 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>ESTOCK ELEMENTARY SCHOOL</b>		<b>17M</b>		
<b>Building</b>	Kindergarten K1	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Kindergarten K1	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Kindergarten K1	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Room K1	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Kindergarten K1	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; some are metal
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Ceiling beams	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	10,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**ESTOCK ELEMENTARY SCHOOL**

**TUSD**  
**17M**

**Inspection Date: 4/5/2018**

<b>Building</b>	Multipurpose	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Multipurpose	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	GOOD	No significant damage; some are metal
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Classroom heater closets	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	Flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
 Technician 17-5918

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	500: Horticulture	<b>Quantity</b>	2,700 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed 1998; building demolished
<b>Description</b>	12x12 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Air conditioning room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: 100's	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Faculty restroom hall	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	406 SF	<b>Comments</b>
<b>Location</b>	Faculty restrooms	<b>Condition</b>	<b>ENCLOSED</b>	Removed June, 2004
<b>Description</b>	Grey floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	4 EA	<b>Comments</b>
<b>Location</b>	Faculty restrooms and hall	<b>Condition</b>	<b>REMOVED</b>	Removed June, 2004
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: 100's	<b>Quantity</b>	5,700 SF	<b>Comments</b>
<b>Location</b>	Hallways	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	Mastic under Black and Gold floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>	
<b>Building</b>	A: 100's	<b>Quantity</b>	288 SF
<b>Location</b>	Library history storage	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	A: 100's	<b>Quantity</b>	216 SF
<b>Location</b>	Library office	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	A: 100's	<b>Quantity</b>	280 SF
<b>Location</b>	Library storage - northeast end	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	A: 100's	<b>Quantity</b>	216 SF
<b>Location</b>	Library workroom	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	A: 100's	<b>Quantity</b>	160 SF
<b>Location</b>	Psychologist	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	HIGH
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 101	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Carpet replace 2015. Mastic and VFT remain.			
<b>Recommended Response Action</b> Routine operations and maintenance			

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 102	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 103	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 104	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 105	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 106	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 107	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 108	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 109	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 110	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 111	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room 112 and "Knightlife"	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 113	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 114	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	400 SF
<b>Location</b>	Room 115 (north)	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	HIGH
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 115 (south) and storage	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	HIGH
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	1 EA
<b>Location</b>	Room 115 (south) storage	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Enclosed inside light fixture
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 116	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 117	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>	
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 118	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	900 SF
<b>Location</b>	Room 119	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 120	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 121	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 122	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	A: 100's	<b>Quantity</b>	840 SF
<b>Location</b>	Room 123	<b>Condition</b>	<b>ENCLOSED</b>
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Carpet replace 2015. Mastic and VFT remain.
<b>Recommended Response Action</b>			Routine operations and maintenance

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**HERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	A: 100's	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Stage area	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 100's	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Video production lab (S. of room 115)	<b>Condition</b>	<b>ENCLOSED</b>	Carpet replace 2015. Mastic and VFT remain.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	25 EA	<b>Comments</b>
<b>Location</b>	Air conditioning room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: 300's	<b>Quantity</b>	75 LF	<b>Comments</b>
<b>Location</b>	Air conditioning room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>		
<b>Building</b>	B: 300's	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Art Gallery and offices above ceiling panels	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>		

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	B: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Inside walls between rooms	<b>Condition</b>	<b>ENCLOSED</b>	Minor quantities in inaccessible areas after summer '93 abatement
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Use caution during renovations
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: 300's	<b>Quantity</b>	1,300 SF	<b>Comments</b>
<b>Location</b>	North hallway	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under gold floor tile
<b>Description</b>	Yellow floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	North hallway above ceiling panels	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: 300's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 301	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 302	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 303	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	B: 300's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 304	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 305	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 306	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	837 SF	<b>Comments</b>
<b>Location</b>	Room 307	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 308	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	783 SF	<b>Comments</b>
<b>Location</b>	Room 309	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	B: 300's	<b>Quantity</b>	810 SF	<b>Comments</b>
<b>Location</b>	Room 310	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	810 SF	<b>Comments</b>
<b>Location</b>	Room 311 and office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	810 SF	<b>Comments</b>
<b>Location</b>	Room 312	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	1,404 SF	<b>Comments</b>
<b>Location</b>	Room 313 and 313A	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room 314	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 300's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Staff restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	B: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	2x4 "Daisy" ceiling panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Administration	<b>Quantity</b>	20 SF	<b>Comments</b>
<b>Location</b>	Attendance hall storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet; SW corner of attendance
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Administration	<b>Quantity</b>	75 SF	<b>Comments</b>
<b>Location</b>	Attendance paper storage	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; NW corner of attendance
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Administration	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Attendance photocopy room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Administration	<b>Quantity</b>	260 SF	<b>Comments</b>
<b>Location</b>	Faculty resource (near 305)	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Administration	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Faculty resource (near 305) storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Verify ACM; routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	B: Administration	<b>Quantity</b>	370 SF	<b>Comments</b>
<b>Location</b>	Nurse	<b>Condition</b>	<b>REMOVED</b>	Removed July, 2005
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Administration	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Office attic	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed in attic; entry in custodial closet
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Office attic	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed in attic; entry in custodial closet. Clean-up and encapsulation was done on 2009.
<b>Description</b>	Fireproofing on beams	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Administration	<b>Quantity</b>	68 SF	<b>Comments</b>
<b>Location</b>	Office supply room	<b>Condition</b>	<b>GOOD</b>	No significant damage; behind reception desk.
<b>Description</b>	9x9 White floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Central workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite counter, sink and under autoclave (oven) at kitchen	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	C1: 200's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Central workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite lab cart	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Central workroom storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C1: 200's	<b>Quantity</b>	10 SF	<b>Comments</b>
<b>Location</b>	Central workroom storage and under most cabinets	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine Operations And Maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	8,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	General science lab	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 201	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 202	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 203	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 204	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 205	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 206	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 207	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	C1: 200's	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Room 208	<b>Condition</b>	<b>GOOD</b>	Sinks removed, counters remaining
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Room 208	<b>Condition</b>	<b>REMOVED</b>	Hood removed
<b>Description</b>	Transite panels on fume hood	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 208-215, halls and workrooms	<b>Condition</b>	<b>REMOVED</b>	Removed 7/03
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	32 SF	<b>Comments</b>
<b>Location</b>	Room 209	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite counter and sink	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Room 215	<b>Condition</b>	<b>GOOD</b>	No significant damage, only one sink remaining
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Room 215	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panels on fume hood	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	C1: 200's	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room 215 storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	2,200 SF	<b>Comments</b>
<b>Location</b>	Rooms 213 & 214 under cabinets	<b>Condition</b>	<b>ENCLOSED</b>	In some areas is expose and loose and broken
<b>Description</b>	9x9 floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine Operations and Maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C1: 200's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Zone #1 Air conditioning and boiler room	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Encapsulate exposed insulation
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C1: 200's	<b>Quantity</b>	142 LF	<b>Comments</b>
<b>Location</b>	Zone #1 Air conditioning and boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C1: 200's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Zone #1 Air conditioning and mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>		

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	C2: 200's	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Faculty resource	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Ceiling panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C2: 200's	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Faculty resource	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	1,172 SF	<b>Comments</b>
<b>Location</b>	Room 216 storage	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 216 storage	<b>Condition</b>	<b>ENCLOSED</b>	One enclosed in light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 216-220	<b>Condition</b>	<b>REMOVED</b>	Removed Spring 1993
<b>Description</b>	2x4 "Daisy" ceiling panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C2: 200's	<b>Quantity</b>	12 SF	<b>Comments</b>
<b>Location</b>	Room 217	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1997
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	C2: 200's	<b>Quantity</b>	1,178 SF	<b>Comments</b>
<b>Location</b>	Room 217 and storage	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 217 storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed in light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	1,178 SF	<b>Comments</b>
<b>Location</b>	Room 218 and pantry	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N/A
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	812 SF	<b>Comments</b>
<b>Location</b>	Room 219	<b>Condition</b>	<b>REMOVED</b>	Removed 7/03
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	840 SF	<b>Comments</b>
<b>Location</b>	Room 220	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C2: 200's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Zone #4 Air conditioning room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	3" pipe insulation	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	N.A.
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	C2: 200's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Zone #4 Air conditioning room	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Snack bar	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Restroom	<b>Condition</b>	<b>GOOD</b>	Light fixture is new, verify presence
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Cafeteria	<b>Condition</b>	<b>GOOD</b>	Minor damage throughout several missing, broken and lifting
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	6 EA	<b>Comments</b>
<b>Location</b>	Cafeteria storage rooms	<b>Condition</b>	<b>GOOD</b>	One enclosed in light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	754 SF	<b>Comments</b>
<b>Location</b>	Food service area	<b>Condition</b>	<b>REMOVED</b>	Removed 12/99
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	225 SF	<b>Comments</b>
<b>Location</b>	Furnace rooms (4)	<b>Condition</b>	<b>GOOD</b>	No significant damage; NW room
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	F: Cafeteria	<b>Quantity</b>	3 EA	<b>Comments</b>
<b>Location</b>	Furnace rooms (SW)	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Kitchen office and storage	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Kitchen restroom and hall	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	4 EA	<b>Comments</b>
<b>Location</b>	Kitchen restroom, hall and storage	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Student restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Cafeteria	<b>Quantity</b>	144 SF	<b>Comments</b>
<b>Location</b>	Teachers cafeteria	<b>Condition</b>	<b>ENCLOSED</b>	Partially removed 12/99
<b>Description</b>	9x9 White floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	G: Boys P.E.	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Equipment room	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Boys P.E.	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof parapet wall	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	Capsheet roofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Boys P.E.	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Training room	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Boys P.E.	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Various	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	Glue spots	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Gym	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Between foyer and student store; above overhang	<b>Condition</b>	<b>ENCLOSED</b>	Small quantities remain enclosed in inaccessible areas
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Use caution during renovations
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Gym	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Electric room	<b>Condition</b>	<b>GOOD</b>	Missing pieces
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Repair or replace
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	H: Gym	<b>Quantity</b>	1,097 SF	<b>Comments</b>
<b>Location</b>	Foyer and student store	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1993
<b>Description</b>	2x4 "Daisy" ceiling panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Gym	<b>Quantity</b>	2,193 SF	<b>Comments</b>
<b>Location</b>	Foyer and student store attic	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1993
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Gym	<b>Quantity</b>	1,097 SF	<b>Comments</b>
<b>Location</b>	Foyer, student store, and restrooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under carpet and tile; removed in restrooms
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Gym	<b>Quantity</b>	4 EA	<b>Comments</b>
<b>Location</b>	Student restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed 7/04
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Girls P.E.	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Halls, restrooms, offices, and equipment storage	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	J: Girls P.E.	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1993
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Girls P.E.	<b>Quantity</b>	160 SF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed 2010
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Girls P.E.	<b>Quantity</b>	15 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1993
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Main dark room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1993
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	360 SF	<b>Comments</b>
<b>Location</b>	Mechanical room (north)	<b>Condition</b>	<b>GOOD</b>	Minor damage at penetration
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	K: 400's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room (north)	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	6 EA	<b>Comments</b>
<b>Location</b>	Mechanical room (north)	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	360 SF	<b>Comments</b>
<b>Location</b>	Mechanical room (southeast)	<b>Condition</b>	<b>GOOD</b>	Minor delamination
<b>Description</b>	Fireproofing	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Monitor damage
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room (southwest)	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	2	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Room 402	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Room 402 duplicating office	<b>Condition</b>	<b>GOOD</b>	Minor damage
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	K: 400's	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room 402 duplicating office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside light fixture
<b>Description</b>	Light heat shield	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Room 402 storage	<b>Condition</b>	<b>GOOD</b>	No significant damage.
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	15 EA	<b>Comments</b>
<b>Location</b>	Room 403 wood shop	<b>Condition</b>	<b>GOOD</b>	No significant damage; at ceiling
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Room 403 wood shop (gym room)	<b>Condition</b>	<b>GOOD</b>	No visible damage but maybe missing tiles under equipment
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room 403 wood shop finishing room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	K: 400's	<b>Quantity</b>	3 EA	<b>Comments</b>
<b>Location</b>	Room 403 wood shop storages (2) and finishing room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside light fixtures
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Verify ACM; routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 404 welding booth walls	<b>Condition</b>	<b>REMOVED</b>	Removed 1997
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 405, 408, storage and darkroom	<b>Condition</b>	<b>REMOVED</b>	Removed 7/03
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 405-408 and main darkroom	<b>Condition</b>	<b>REMOVED</b>	Removed 1993
<b>Description</b>	2x4 ceiling panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K: 400's	<b>Quantity</b>	80 SF	<b>Comments</b>
<b>Location</b>	Room 405-408 office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>FOOTHILL HIGH SCHOOL</b>		<b>17B</b>		
<b>Building</b>	K: 400's	<b>Quantity</b>	2,100 SF	<b>Comments</b>
<b>Location</b>	Room 406 choir, hall, storages, and restrooms	<b>Condition</b>	<b>GOOD</b>	No significant damage; removed in restrooms and robe storage
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	11 EA	<b>Comments</b>
<b>Location</b>	Room 406 dressing, restroom, and robe storage	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Light heat shields	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 407 Band	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet; exposed in storage
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	2x3	<b>Comments</b>
<b>Location</b>	Room 408 Photo, on work table	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Adjacent to windows	<b>Condition</b>	<b>GOOD</b>	No significant damage, removed in Boy's and Girl's Locker Rooms
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**FOOTHILL HIGH SCHOOL**

**17B**

<b>Building</b>	Throughout	<b>Quantity</b>	40 EA	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Patching mastic	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**GUIN FOSS SCHOOL**

**17J**

<b>Building</b>	Building A: Administration	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet and new floor tile
<b>Description</b>	9x9 Brown floor tile and/or mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building B: Kindergarten	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Restrooms	<b>Condition</b>	<b>REMOVED</b>	Removed 6/04
<b>Description</b>	12x12 Orange floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building B: Kindergarten	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room A2 heater room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building B: Kindergarten	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Throughout except A2 restrooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building C: Rooms B1 - B4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building C: Rooms B1 - B4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed 1996-97
<b>Description</b>	Cove base	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>GUIN FOSS SCHOOL</b>		<b>17J</b>		
<b>Building</b>	Building C: Rooms B1 - B4	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building D1: Rooms C1 - C4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Custodial room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panel	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D1: Rooms C1 - C4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	Minor damage: <1% ACM, some loose @ room 4
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D1: Rooms C1 - C4	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 1997
<b>Description</b>	Cove base	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D1: Rooms C1 - C4	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D2: Rooms D1 - D4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**GUIN FOSS SCHOOL**

**17J**

<b>Building</b>	Building D2: Rooms D1 - D4	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Food service	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by Tan 12x12 floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building D2: Rooms D1 - D4	<b>Quantity</b>	3,400 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	32 SF	<b>Comments</b>
<b>Location</b>	Above windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Library	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	45 SF	<b>Comments</b>
<b>Location</b>	Library restroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by new sheet vinyl
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Main room walls	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied wall plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**GUIN FOSS SCHOOL**

**17J**

<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	2 LF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed; may remain inside walls
<b>Description</b>	Straight run pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Verify presence
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	3 LF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Gasket	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F: Rooms E1 - E4	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F: Rooms E1 - E4	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



***AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

---

**Tustin Unified School District  
GUIN FOSS SCHOOL**

**TUSD  
17J**


**Inspection Date: 4/5/2018**

---

**David Johnson Certified Site Surveillance  
Technician 17-5918**

---

***Inspector Signature***



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>HEIDEMAN ELEMENTARY SCHOOL</b>		<b>170</b>		
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Faculty lounge	<b>Condition</b>	<b>REMOVED</b>	Removed; building demolished
<b>Description</b>	12x12 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed; building demolished
<b>Description</b>	Floor tile and linoleum	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	8,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Kindergarten room 1	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	12 SF	<b>Comments</b>
<b>Location</b>	Kindergarten workroom	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panel	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	324 SF	<b>Comments</b>
<b>Location</b>	Room B5	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEIDEMAN ELEMENTARY SCHOOL**

**170**

<b>Building</b>	B	<b>Quantity</b>	44 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; some are metal
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Patching mastic	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	F	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEWES MIDDLE SCHOOL**

**17E**

<b>Building</b>	A: Administration	<b>Quantity</b>	189 SF	<b>Comments</b>
<b>Location</b>	Health office and restrooms	<b>Condition</b>	<b>REMOVED</b>	Remove 09/00
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	1	<b>Comments</b>
<b>Location</b>	Interior restroom	<b>Condition</b>	<b>REMOVED</b>	Removed 7/07
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Office area	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenanc
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	4 EA	<b>Comments</b>
<b>Location</b>	Offices and workroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	205 SF	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>ENCLOSED</b>	New carpeting over tile. New lounge area. Observed 2018
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	2,400 SF	<b>Comments</b>
<b>Location</b>	Room 08, 10	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEWES MIDDLE SCHOOL**

**17E**

<b>Building</b>	B: Classrooms	<b>Quantity</b>	1,200 SF	<b>Comments</b>
<b>Location</b>	Room 09	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 09 at Kiln	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Room 10	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	1,200 SF	<b>Comments</b>
<b>Location</b>	Room 11	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	8 EA	<b>Comments</b>
<b>Location</b>	Room 11	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	2,400 SF	<b>Comments</b>
<b>Location</b>	Room 11-12 Prep room	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEWES MIDDLE SCHOOL**

**17E**

<b>Building</b>	B: Classrooms	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 11-12 Prep room	<b>Condition</b>	<b>REMOVED</b>	REMOVED
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Room 11-12 Prep room	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Room 12	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	Transite counters and sinks	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: classrooms	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Room 12	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Library	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Library storage room/custodian	<b>Condition</b>	<b>GOOD</b>	Minor damage; obscured
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Library	<b>Quantity</b>	240 SF	<b>Comments</b>
<b>Location</b>	Library workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**HERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>HEWES MIDDLE SCHOOL</b>		<b>17E</b>		
<b>Building</b>	E: Library	<b>Quantity</b>	4,800 SF	<b>Comments</b>
<b>Location</b>	Library, workroom, and computer room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	2,200 SF	<b>Comments</b>
<b>Location</b>	Room F-1, pantry, and storeroom	<b>Condition</b>	<b>REMOVED</b>	REMOVED 7/14
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Room F-2 and F-4	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Classrooms	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Room F-3 wood shop storage	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Locker rooms	<b>Quantity</b>	305 SF	<b>Comments</b>
<b>Location</b>	Boys coaches' office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Locker rooms	<b>Quantity</b>	16 LF	<b>Comments</b>
<b>Location</b>	Courtyard furnace room	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Gaskets	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEWES MIDDLE SCHOOL**

**17E**

<b>Building</b>	G: Locker rooms	<b>Quantity</b>	33 EA	<b>Comments</b>
<b>Location</b>	Courtyard furnace room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Locker rooms	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Courtyard furnace room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Locker rooms	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Locker rooms	<b>Quantity</b>	700 SF	<b>Comments</b>
<b>Location</b>	Girls coaches' office	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	3,500 SF	<b>Comments</b>
<b>Location</b>	Multipurpose	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Multipurpose stage and two storage rooms	<b>Condition</b>	<b>GOOD</b>	Minor damage, many replaced @ stage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>HEWES MIDDLE SCHOOL</b>			<b>17E</b>	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Multipurpose stage storage rooms	<b>Condition</b>	<b>GOOD</b>	West storage door removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Room H-1	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Room H-2 Band	<b>Condition</b>	<b>GOOD</b>	No significant damage, some replaced
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors; some have been removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Verify presence; routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**HEWES MIDDLE SCHOOL**

**17E**

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>REMOVED</b>	Removed 7/04
<b>Description</b>	Patching mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	1,600 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>HILLVIEW HIGH SCHOOL</b>		<b>17F</b>		
<b>Building</b>	B	<b>Quantity</b>	1000 SF	<b>Comments</b>
<b>Location</b>	Classroom B-1	<b>Condition</b>	<b>REMOVED</b>	Removed during Tennis Court Renovation Project
<b>Description</b>	Floor Tile Mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>REMOVED</b>	No significant damage
<b>Description</b>	Flex collar	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Kiln room outside B-1	<b>Condition</b>	<b>REMOVED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>		<b>Comments</b>
<b>Location</b>	Kiln room outside B-1	<b>Condition</b>	<b>REMOVED</b>	Removed Prior to Sept. 2011
<b>Description</b>	Asbestos glove	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>	35 SF	<b>Comments</b>
<b>Location</b>	Kiln room outside B-1	<b>Condition</b>	<b>REMOVED</b>	At walls around kiln (not attach)
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	575 SF	<b>Comments</b>
<b>Location</b>	Wood shop student store	<b>Condition</b>	<b>REMOVED</b>	Removed 8/10
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>HILLVIEW HIGH SCHOOL</b>		<b>17F</b>		
<b>Building</b>	B and C	<b>Quantity</b>	6,000 SF	<b>Comments</b> Minor damage; <1% ACM. Some cracks and peeling off
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Bldg B- Removed during demolition Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B and C	<b>Quantity</b>	110 SF	<b>Comments</b> No significant damage
<b>Location</b>	Under and over windows	<b>Condition</b>	<b>GOOD</b>	
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Bldg B- Removed prior to demolition Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	200 LF	<b>Comments</b> Seen above ceiling panels in rooms C-6 and C-4
<b>Location</b>	Attic above ceilings panels	<b>Condition</b>	<b>ENCLOSED</b>	
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> 10 LF Removed during renovation Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C	<b>Quantity</b>	35 LF	<b>Comments</b> Removed between 8/13 & 1/14
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C	<b>Quantity</b>	28 LF	<b>Comments</b> Removed between 8/13 & 1/14
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

***AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

---

**Tustin Unified School District  
HILLVIEW HIGH SCHOOL**

**TUSD  
17F**

**Inspection Date: 4/5/2018**

---

**David Johnson Certified Site Surveillance  
Technician 17-5918**

---

***Inspector Signature***



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**LAMBERT SCHOOL**

**17W**

<b>Building</b>	A: Administration	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	Verify presence
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	8 LF	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	N.A.
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Nurse's office	<b>Condition</b>	<b>REMOVED</b>	Removed 7/04
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	175 SF	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet.
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**LAMBERT SCHOOL**

**17W**

<b>Building</b>	B: Room 32	<b>Quantity</b>	6 LF	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed Spring, 1997
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B: Room 32	<b>Quantity</b>	1,160 SF	<b>Comments</b>
<b>Location</b>	Room 32	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Room 32	<b>Quantity</b>	80 SF	<b>Comments</b>
<b>Location</b>	Room 32 office	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Classrooms 1-6	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Classrooms 1-6	<b>Quantity</b>	10 LF	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	Minor Damage
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Monitor damage
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Classrooms 1-6	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Room 4 workroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under beige floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>LAMBERT SCHOOL</b>		<b>17W</b>		
<b>Building</b>	C: Classrooms 1-6	<b>Quantity</b>	6,000 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under carpet and floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Classrooms 1-6	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Classrooms 13-18	<b>Quantity</b>	13 EA	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	No significant damage.
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D: Classrooms 13-18	<b>Quantity</b>	6 LF	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	Minor damage, whole piece is on ground on side of equipment.
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Remove
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D: Classrooms 13-18	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Over and under windows	<b>Condition</b>	<b>GOOD</b>	Cracked panels at rooms 13 and 14
<b>Description</b>	Transite window panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Classrooms 19-26	<b>Quantity</b>	6 LF	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	Deteriorating
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Monitor damage
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**LAMBERT SCHOOL**

**17W**

<b>Building</b>	E: Classrooms 19-26	<b>Quantity</b>	12 EA	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>GOOD</b>	Old water damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Monitor damage
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<hr/>				
<b>Building</b>	E: Classrooms 19-26	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Over and under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage.
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>LOMA VISTA ELEMENTARY SCHOOL</b>			<b>17N</b>	
<b>Building</b>	Administration	<b>Quantity</b>	8,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	1,200 SF	<b>Comments</b>
<b>Location</b>	Nurse's office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Supply room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Brown floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	9 SF	<b>Comments</b>
<b>Location</b>	Teachers' workroom	<b>Condition</b>	<b>REMOVED</b>	Removed 1998
<b>Description</b>	Transite wall panel	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	20 SF	<b>Comments</b>
<b>Location</b>	Teachers' workroom - under kiln	<b>Condition</b>	<b>REMOVED</b>	No longer present
<b>Description</b>	Transite panel	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	4,500 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>LOMA VISTA ELEMENTARY SCHOOL</b>			<b>17N</b>	
<b>Building</b>	Administration	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed 7/04
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	20 LF	<b>Comments</b>
<b>Location</b>	Water heater closet	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; enclosed in attic
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Administration	<b>Quantity</b>	16 LF	<b>Comments</b>
<b>Location</b>	Water heater closet	<b>Condition</b>	<b>GOOD</b>	Exposed ends and minor tearing
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Encapsulate exposed ends
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Administration	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Water heater closet	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>	8,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	Minor damage; <1% ACM
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>LOMA VISTA ELEMENTARY SCHOOL</b>		<b>17N</b>		
<b>Building</b>	B	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Main field roof	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Tar and gravel roofing	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Rooms B1 to B4	<b>Condition</b>	<b>ENCLOSED</b>	Loose and missing tiles in closets; enclosed in classrooms
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Repair or remove in closets
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	20 LF	<b>Comments</b>
<b>Location</b>	Custodial room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed in attic above HWH
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	8,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Food service C-1	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 12 X 12 white floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>LOMA VISTA ELEMENTARY SCHOOL</b>		<b>17N</b>		
<b>Building</b>	C	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Rooms C1 to C4	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C, D, Multi	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D	<b>Quantity</b>	3,600 SF	<b>Comments</b>
<b>Location</b>	Rooms D1 to D5	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	8" pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E	<b>Quantity</b>	8 LF	<b>Comments</b>
<b>Location</b>	HWH Closet (behind E1-E2)	<b>Condition</b>	<b>GOOD</b>	Exposed ends and minor tearing
<b>Description</b>	3" pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Encapsulate exposed ends
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>LOMA VISTA ELEMENTARY SCHOOL</b>		<b>17N</b>		
<b>Building</b>	E	<b>Quantity</b>	950 SF	<b>Comments</b>
<b>Location</b>	Room E1	<b>Condition</b>	<b>GOOD</b>	120 SF exposed one is broken; rest enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance Hazard Ranking</b>	HIGH *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	950 SF	<b>Comments</b>
<b>Location</b>	Room E2	<b>Condition</b>	<b>GOOD</b>	240 SF exposed; rest enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance Hazard Ranking</b>	HIGH *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	80	<b>Comments</b>
<b>Location</b>	Rooms E1- E2 workroom	<b>Condition</b>	<b>GOOD</b>	Minor damage at doorway
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance Hazard Ranking</b>	HIGH *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	4,500 SF	<b>Comments</b>
<b>Location</b>	Rooms E3 to E7	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance Hazard Ranking</b>	LOW *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance Hazard Ranking</b>	MOD *	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Kindergarten	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance Hazard Ranking</b>	N.A.	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	N.A.
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**LOMA VISTA ELEMENTARY SCHOOL**

**17N**

<b>Building</b>	F: Kindergarten	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Kindergarten	<b>Quantity</b>	2,200 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet and new floor tile
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Kindergarten	<b>Quantity</b>	192 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	10,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G: Multipurpose	<b>Quantity</b>	13 SF	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>GOOD</b>	No significant damage; located on old ducts
<b>Description</b>	Insulating paper	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**LOMA VISTA ELEMENTARY SCHOOL**

**17N**

<b>Building</b>	G: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Spray-applied floor tile	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	SURF	N.A.
		<b>Friable Non-Friable</b>	F	

---

<b>Building</b>	G: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	9x9 Grey floor tile	<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>		

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
		<b>Potential for Disturbance</b>	N.A.	
<b>Description</b>	Expansion joints	<b>Hazard Ranking</b>		<b>Recommended Response Action</b>
		<b>Type</b>	TSI	N.A.
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>NELSON ELEMENTARY SCHOOL</b>			<b>17V</b>	
<b>Building</b>	Building A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Straight run pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building A: Administration	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Firedoor insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building A: Administration	<b>Quantity</b>	120 SF	<b>Comments</b>
<b>Location</b>	Nurse's office	<b>Condition</b>	<b>REMOVED</b>	Removed 6/04
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A: Administration	<b>Quantity</b>	69 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; some are metal
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building A: Administration	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Workroom	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building C	<b>Quantity</b>	9 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe elbow insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>NELSON ELEMENTARY SCHOOL</b>		<b>17V</b>		
<b>Building</b>	Building C	<b>Quantity</b>	7 LF 6"D	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	Deteriorating
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Monitor damage; do not store objects against insulation
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building C	<b>Quantity</b>	24 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building D	<b>Quantity</b>	20 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe elbow insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building D	<b>Quantity</b>	5 LF 6"D	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>DAMAGED</b>	Deteriorating
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Repair or replace
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building D	<b>Quantity</b>	147 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transit panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building E	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>NELSON ELEMENTARY SCHOOL</b>			<b>17V</b>	
<b>Building</b>	Building E	<b>Quantity</b>	20 EA	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	Minor water damage
<b>Description</b>	Pipe elbow insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E	<b>Quantity</b>	6 LF 6"D	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>DAMAGED</b>	Torn; deteriorating, debris
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	4	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Repair or remove
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building E	<b>Quantity</b>	132 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F	<b>Quantity</b>	3 EA	<b>Comments</b>
<b>Location</b>	Exterior storage rooms	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Firedoor insulation	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building F	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 19	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operation and maintenance
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 19 mechanical room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	1	<b>Recommended Response Action</b>
		<b>Type</b>	TSI	Routine operation and maintenance
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>NELSON ELEMENTARY SCHOOL</b>			<b>17V</b>	
<b>Building</b>	Building F	<b>Quantity</b>	4 LF	<b>Comments</b>
<b>Location</b>	Room 19 mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building F	<b>Quantity</b>	160 SF	<b>Comments</b>
<b>Location</b>	Room 19-20 workroom and storage	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F	<b>Quantity</b>	300SF	<b>Comments</b>
<b>Location</b>	Room 20	<b>Condition</b>	<b>ENCLOSED</b>	Removed or enclosed by new floor tile
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building F	<b>Quantity</b>	7 LF	<b>Comments</b>
<b>Location</b>	Room 20 mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	4	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building F	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 20 mechanical room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operation and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building F	<b>Quantity</b>	400 SF	<b>Comments</b>
<b>Location</b>	Room 21 and office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**NELSON ELEMENTARY SCHOOL**

**TUSD**  
**17V**

**Inspection Date: 4/5/2018**

<b>Building</b>	Building F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 21 mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer, 1997
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Building F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 21 mechanical room	<b>Condition</b>	<b>REMOVED</b>	Removed Summer, 1997
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Firedoor insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

David Johnson Certified Site Surveillance  
 Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>SUPPORT SERVICES FACILITY</b>		<b>17P</b>	
<b>Building</b>	Support services	<b>Quantity</b>	525 SF
<b>Location</b>	A.V. shop and closet	<b>Condition</b>	<b>GOOD</b>
		<b>Potential for Disturbance</b>	HIGH
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> No significant damage			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	Support services	<b>Quantity</b>	40 SF
<b>Location</b>	Custodial office	<b>Condition</b>	<b>GOOD</b>
		<b>Potential for Disturbance</b>	HIGH
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Minor damage			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	Support services	<b>Quantity</b>	400 SF
<b>Location</b>	Entrance and offices	<b>Condition</b>	<b>ENCLOSED</b>
		<b>Potential for Disturbance</b>	LOW
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Enclosed by carpet			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	Support services	<b>Quantity</b>	720 SF
<b>Location</b>	Hall to transportation	<b>Condition</b>	<b>GOOD</b>
		<b>Potential for Disturbance</b>	HIGH
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Cracks and bubbling			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	Support services	<b>Quantity</b>	113 SF
<b>Location</b>	Hall to warehouse	<b>Condition</b>	<b>GOOD</b>
		<b>Potential for Disturbance</b>	HIGH
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> Minor damage			
<b>Recommended Response Action</b> Routine operations and maintenance			
<b>Building</b>	Support services	<b>Quantity</b>	300 SF
<b>Location</b>	Locksmith	<b>Condition</b>	<b>GOOD</b>
		<b>Potential for Disturbance</b>	HIGH
<b>Description</b>	12x12 Beige floor tile	<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b> No significant damage			
<b>Recommended Response Action</b> Routine operations and maintenance			

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**SUPPORT SERVICES FACILITY**

**TUSD**  
**17P**

**Inspection Date: 4/5/2018**

<b>Building</b>	Support services	<b>Quantity</b>	480 SF	<b>Comments</b>
<b>Location</b>	Lounge	<b>Condition</b>	<b>GOOD</b>	Minor damage at patio doors
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Support services	<b>Quantity</b>	120 SF	<b>Comments</b>
<b>Location</b>	Plan room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Support services	<b>Quantity</b>	120 SF	<b>Comments</b>
<b>Location</b>	Plan vault room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Support services	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Warehouse office	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
 Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>THORMAN ELEMENTARY SCHOOL</b>		<b>17D</b>		
<b>Building</b>	Building A: 30's	<b>Quantity</b>	740 LF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Baseboard mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building B: 20's	<b>Quantity</b>	450 SF	<b>Comments</b>
<b>Location</b>	Kitchen	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by 12x12 red floor tile
<b>Description</b>	Mastic under red floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Building C: 10's	<b>Quantity</b>	40 SF	<b>Comments</b>
<b>Location</b>	Workroom 314 under kiln	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panel	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Exterior window panels	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof mansard	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2008
<b>Description</b>	Transite shingles	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operation and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**THORMAN ELEMENTARY SCHOOL**

**17D**

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof patches and penetrations	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2008
<b>Description</b>	Mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>		
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof walkways	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2008
<b>Description</b>	Black composition roofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operation and maintenance
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	A: 210-213	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: 210-213	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Interior walls	<b>Condition</b>	<b>REMOVED</b>	Removed, Summer 2010 Mod.
<b>Description</b>	Drywall mud	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Athletic director's trailer	<b>Quantity</b>	264 SF	<b>Comments</b>
<b>Location</b>	Office, restroom, storage	<b>Condition</b>	<b>REMOVED</b>	Removed 8/02; trailer demolished
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 110-113	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: 110-113	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Interior walls	<b>Condition</b>	<b>REMOVED</b>	Removed, Summer 2010 Mod.
<b>Description</b>	Drywall mud	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: 220-227	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	C: 220-227	<b>Quantity</b>	10,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: 220-227	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Interior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Drywall mud	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Custodial	<b>Quantity</b>	4 LF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Custodial	<b>Quantity</b>	820 SF	<b>Comments</b>
<b>Location</b>	Restroom	<b>Condition</b>	<b>GOOD</b>	No significant damage, innacc. 7/2011
<b>Description</b>	Ceiling plaster	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Custodial	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Room 110 Audio visual	<b>Condition</b>	<b>REMOVED</b>	
<b>Description</b>	9x9 Brown floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Removed 2016 (DEMOLISHED)
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: 120-125	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Attic walls	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; enclosed in attic, inaccessible 07/2011
<b>Description</b>	Drywall mud	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>		<b>17A</b>		
<b>Building</b>	D: 120-125	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: 120-125	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Room 120 dressing rooms, storage and ticket office	<b>Condition</b>	<b>GOOD</b>	Minor damage in dressing rooms, inaccessible 07/2011
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: 120-125	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 120 stage	<b>Condition</b>	<b>GOOD</b>	No significant damage, inaccessible 07/2011
<b>Description</b>	Spot light wire insulation	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	3	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Administration	<b>Quantity</b>	38 EA	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Administration	<b>Quantity</b>	20 SF	<b>Comments</b>
<b>Location</b>	Closet near resources	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Closets across from nurse (2)	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	E: Administration	<b>Quantity</b>	204 SF	<b>Comments</b>
<b>Location</b>	Copy room	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	65 SF	<b>Comments</b>
<b>Location</b>	Kitchenette	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Mail room (near principals office)	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	10LF	<b>Comments</b>
<b>Location</b>	Mail room heater closet	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Mail room heater closet	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	E: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room 5	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	Duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Mechanical room 5	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Administration	<b>Quantity</b>	634 SF	<b>Comments</b>
<b>Location</b>	Nurse's offices	<b>Condition</b>	<b>REMOVED</b>	Removed 6/04
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	87 SF	<b>Comments</b>
<b>Location</b>	Paper storage	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Phone system and electric room	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Administration	<b>Quantity</b>	98 SF	<b>Comments</b>
<b>Location</b>	Security room	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2015
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>		<b>17A</b>	
<b>Building</b>	E: Administration	<b>Quantity</b>	10,000 SF
<b>Location</b>	Throughout except as noted	<b>Condition</b>	<b>REMOVED</b>
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Removed summer 2015
<b>Recommended Response Action</b>			N.A.
<b>Building</b>	E: Administration	<b>Quantity</b>	100 SF
<b>Location</b>	Vault	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	HIGH
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			Removed summer 2015
<b>Recommended Response Action</b>			N.A.
<b>Building</b>	F: 230-234	<b>Quantity</b>	5,000 SF
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage; <1% ACM
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	F: 230-234	<b>Quantity</b>	300 SF
<b>Location</b>	Room 232 exterior kilns	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	MISC
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage, one broken. Inacc. 07/2011
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	G: 130-138	<b>Quantity</b>	10,000 SF
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD
		<b>Hazard Ranking</b>	*
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	NF
<b>Comments</b>			No significant damage; <1% ACM
<b>Recommended Response Action</b>			Routine operations and maintenance
<b>Building</b>	G: 130-138	<b>Quantity</b>	10,000 SF
<b>Location</b>	Room 133 and restroom	<b>Condition</b>	<b>GOOD</b>
<b>Description</b>	Spray-applied acoustic ceiling plaster	<b>Potential for Disturbance</b>	LOW
		<b>Hazard Ranking</b>	1
		<b>Type</b>	SURF
		<b>Friable Non-Friable</b>	F
<b>Comments</b>			No significant damage, innacc. 07/2011
<b>Recommended Response Action</b>			Routine operations and maintenance

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>		<b>17A</b>		
<b>Building</b>	G: 130-138	<b>Quantity</b>	85 SF	<b>Comments</b>
<b>Location</b>	Room 136	<b>Condition</b>	<b>GOOD</b>	No significant damage; inacc. 07/2011
<b>Description</b>	Spray-applied acoustic ceiling plaster	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	Routine operations and maintenance
<b>Building</b>	G: Custodial Room	<b>Quantity</b>	30 SF	<b>Comments</b>
<b>Location</b>	Custodial Room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panel	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	Routine Operations And Maintenance
<b>Building</b>	H: 604-609	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	Routine operations and maintenance
<b>Building</b>	H: 604-609	<b>Quantity</b>	20 EA	<b>Comments</b>
<b>Location</b>	Inside walls	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	Verify presence; routine operations and maintenance
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	10 EA	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; enclosed in attic
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	Routine operations and maintenance

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	I: Cafeteria	<b>Quantity</b>	7,200 SF	<b>Comments</b>
<b>Location</b>	Cafeteria	<b>Condition</b>	<b>REMOVED</b>	Removed 12/2009, except in closets (lifting)
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Cafeteria stage classroom & steps	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	36 SF	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	8 LF	<b>Comments</b>
<b>Location</b>	Exterior mechanical room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed in attic
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	350 SF	<b>Comments</b>
<b>Location</b>	Faculty dining (north side)	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	I: Cafeteria	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Faculty dining (south side)	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N/A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Hall to faculty dining	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N/A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Kitchen office	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N/A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	250 SF	<b>Comments</b>
<b>Location</b>	Kitchen restrooms, locker room and hall	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N/A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	I: Cafeteria	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Serving area	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N/A
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	45 EA	<b>Comments</b>
<b>Location</b>	Boiler and locker room	<b>Condition</b>	<b>GOOD</b>	Some removed; likely inside walls also.
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	5	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>			<b>17A</b>	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	2	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	304 SF	<b>Comments</b>
<b>Location</b>	Coaches office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	15,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Gym storage and custodial	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	293 SF	<b>Comments</b>
<b>Location</b>	Gym vestibule	<b>Condition</b>	<b>REMOVED</b>	Removed 11/00
<b>Description</b>	9x9 Beige floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J: Boy's locker room and gym	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Locker room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by ceiling tiles, one tile is missing
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Verify ACM; routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>		<b>17A</b>		
<b>Building</b>	J1: Girl's locker room	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J1: Girl's locker room	<b>Quantity</b>	39 EA	<b>Comments</b>
<b>Location</b>	Boiler room and attic	<b>Condition</b>	<b>GOOD</b>	13 in boiler room; rest enclosed in attic
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	J1: Girl's locker room	<b>Quantity</b>	900 SF	<b>Comments</b>
<b>Location</b>	Coaches offices and first aid	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	J1: Girl's locker room	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Locker room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by ceiling tiles, some exposed.
<b>Description</b>	Ceiling tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Verify ACM; routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	All classrooms except 415 storage and office	<b>Condition</b>	<b>REMOVED</b>	Removed during Summer 2010 Mod.
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Exterior heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed during Summer 2010 Mod.
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	K: 400's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	K1 - K4: 300's	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	Minor damage; <1% ACM, some cracking and peeling at overhang
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K1 - K4: 300's	<b>Quantity</b>	200 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2014
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K1 - K4: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 321 heater closet	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>		
<b>Building</b>	K1 - K4: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed summer 2014
<b>Description</b>	9x9 floor tile and/or mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K1 - K4: 300's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>			<b>17A</b>	
<b>Building</b>	L: Library	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Exterior heater room	<b>Condition</b>	<b>GOOD</b>	No significant damage. Inaccessible 07/2011
<b>Description</b>	Flex joint	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	L: Library	<b>Quantity</b>	8 LF	<b>Comments</b>
<b>Location</b>	Exterior heater room	<b>Condition</b>	<b>GOOD</b>	Minor damage, inaccessible 07/2011
<b>Description</b>	Aircell insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	L: Library	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM, broken & loose in back
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	L: Library	<b>Quantity</b>	736 SF	<b>Comments</b>
<b>Location</b>	Library storeroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by red floor tile
<b>Description</b>	Floor tile mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	L: Library	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Student store	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	L: Library	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	L: Library	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Throughout except storeroom	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	N: Stadium	<b>Quantity</b>	100 SF	<b>Comments</b>
<b>Location</b>	Attic boiler room	<b>Condition</b>	<b>ENCLOSED</b>	Debris under boiler is not ACM
<b>Description</b>	Boiler insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	N: Stadium	<b>Quantity</b>	5 SF	<b>Comments</b>
<b>Location</b>	Attic boiler room	<b>Condition</b>	<b>ENCLOSED</b>	Inside fan cabinet
<b>Description</b>	Flex joints	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	N: Stadium	<b>Quantity</b>	150 SF	<b>Comments</b>
<b>Location</b>	Attic boiler room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	N: Stadium	<b>Quantity</b>	130 SF	<b>Comments</b>
<b>Location</b>	Attic boiler room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	N: Stadium	<b>Quantity</b>	15 EA	<b>Comments</b>
<b>Location</b>	Attic boiler room	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	P: 600's	<b>Quantity</b>	6 LF	<b>Comments</b>
<b>Location</b>	Mechanical room	<b>Condition</b>	<b>GOOD</b>	No significant damage, innacc. 07/2011
<b>Description</b>	Aircell insulation on exhaust duct	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	P: 600's	<b>Quantity</b>	1,421 SF	<b>Comments</b>
<b>Location</b>	Room 600 and storages (2)	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	P: 600's	<b>Quantity</b>	1,116 SF	<b>Comments</b>
<b>Location</b>	Room 601 and office	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	P: 600's	<b>Quantity</b>	1,116 SF	<b>Comments</b>
<b>Location</b>	Room 602	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	P: 600's	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Room 603 dressing and uniform storage	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N/A
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	P: 600's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 604	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN HIGH SCHOOL</b>			<b>17A</b>	
<b>Building</b>	Throughout	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Heater closets	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors, innacc. 07/2011
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	500 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; 3 broken @ room # 232
<b>Description</b>	Transite window panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Central area	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Central area attic (near 525)	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	6 inch	<b>Comments</b>
<b>Location</b>	Central area attic (near 525)	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	32 EA	<b>Comments</b>
<b>Location</b>	Central area attic (near 525)	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	X: 500's	<b>Quantity</b>	1,800 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,669 SF	<b>Comments</b>
<b>Location</b>	Room 520	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 520 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Room 520 conference room	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	180 SF	<b>Comments</b>
<b>Location</b>	Room 520 conference room	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 521 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	X: 500's	<b>Quantity</b>	1,769 SF	<b>Comments</b>
<b>Location</b>	Room 521, prep, and custodial room	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	80 SF	<b>Comments</b>
<b>Location</b>	Room 521-522 oxidizer storage	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,200 SF	<b>Comments</b>
<b>Location</b>	Room 522	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Room 522 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	120 SF	<b>Comments</b>
<b>Location</b>	Room 522-523 prep	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,200 SF	<b>Comments</b>
<b>Location</b>	Room 523	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	X: 500's	<b>Quantity</b>	1,500 SF	<b>Comments</b>
<b>Location</b>	Room 523 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	50 SF	<b>Comments</b>
<b>Location</b>	Room 523-524 storage	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Room 523-524 storage attic	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Room 523-524 storage attic	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Aircell and paper tape insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,669 SF	<b>Comments</b>
<b>Location</b>	Room 524	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 524 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	X: 500's	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 524 prep (off center)	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 524 prep (off center)	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	1,669 SF	<b>Comments</b>
<b>Location</b>	Room 525	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 525 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	X: 500's	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 525-526 prep	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	X: 500's	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Room 525-526 storage and closet	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN HIGH SCHOOL**

**17A**

<b>Building</b>	X: 500's	<b>Quantity</b>	1,669 SF	<b>Comments</b>
<b>Location</b>	Room 526	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	X: 500's	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Room 526 ceiling and upper walls	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Spray-applied plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<hr/>				
<b>Building</b>	X: 500's	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed July 2011, bldg. demolished
<b>Description</b>	Base board mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN MEMORIAL ELEMENTARY SCHOOL</b>			<b>17S</b>	
<b>Building</b>	A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Offices	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	12x12 White floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Classrooms	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Attic	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Classrooms	<b>Quantity</b>	15 SF	<b>Comments</b>
<b>Location</b>	Room 5 sink counter	<b>Condition</b>	<b>REMOVED</b>	Removed, 2006
<b>Description</b>	Brown sheet vinyl	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Classrooms	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 5-7	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Classrooms	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 8-10	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Rooms 11 and 13 storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN MEMORIAL ELEMENTARY SCHOOL</b>			<b>17S</b>	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 11-14	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B: Classrooms	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 15-18	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Brown floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial storage	<b>Condition</b>	<b>SIGNIFICANT DAMAGE</b>	Door is coming apart to reveal interior insulation
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	6	Repair or Replace
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Custodial storage above HWH	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	2	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof - west end	<b>Condition</b>	<b>REMOVED</b>	Removed Summer, 2011
<b>Description</b>	Tar and gravel roofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by cove base; <1% ACM
<b>Description</b>	Cove base mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN MEMORIAL ELEMENTARY SCHOOL</b>			<b>17S</b>	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Grey floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Kindergarten	<b>Quantity</b>	45 SF	<b>Comments</b>
<b>Location</b>	Under exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	600 SF	<b>Comments</b>
<b>Location</b>	Electric room	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	Black mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	3 LF	<b>Comments</b>
<b>Location</b>	Heater closet - North side	<b>Condition</b>	<b>GOOD</b>	No significant damage, visible on roof
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Inside walls	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Main room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied acoustic ceiling and wall plaster	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		
		<b>Type</b>	SURF	N.A.
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>TUSTIN MEMORIAL ELEMENTARY SCHOOL</b>			<b>17S</b>	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Multipurpose	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage, under stage
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Speech above ceiling	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed above ceiling; removed inside walls
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	1	
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	E: Classrooms	<b>Quantity</b>	54 SF	<b>Comments</b>
<b>Location</b>	Rooms 20-22 under windows	<b>Condition</b>	<b>GOOD</b>	Panels cracked at rooms 20 and 22
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Classrooms	<b>Quantity</b>	4,500 SF	<b>Comments</b>
<b>Location</b>	Rooms 20-24	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Green floor tile and mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Classrooms	<b>Quantity</b>	1,000 LF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by cove base; <1% ACM
<b>Description</b>	Cove base mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b> Routine operations and maintenance
		<b>Hazard Ranking</b>	*	
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	All buildings except C and E	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**TUSTIN MEMORIAL ELEMENTARY SCHOOL**

**17S**

<b>Building</b>	Throughout	<b>Quantity</b>	1,000 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>REMOVED</b>	Removed summer, 2011
<b>Description</b>	Grey patching mastic	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	N.A.
		<b>Friable Non-Friable</b>	NF	
<hr/>				
<b>Building</b>	Walkways	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roofs	<b>Condition</b>	<b>REMOVED</b>	Removed summer, 2011
<b>Description</b>	Roofing felt	<b>Potential for Disturbance</b>	N.A.	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	N.A.
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
Technician 17-5918

*Inspector Signature*



\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>UTT INTERMEDIATE SCHOOL</b>		<b>171</b>		
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Cafeteria	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Linoleum	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Counseling	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside heater and custodial room doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater Room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Gaskets	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater Room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater Room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Multipurpose	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed under ceiling tiles
<b>Description</b>	Drywall joint compound	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District  
UTT INTERMEDIATE SCHOOL**

**TUSD  
171**

**Inspection Date: 4/5/2018**

<b>Building</b>	A	<b>Quantity</b>	5	<b>Comments</b>
<b>Location</b>	Multipurpose restrooms	<b>Condition</b>	REMOVED	Removed 2006
<b>Description</b>	Light insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	5 EA	<b>Comments</b>
<b>Location</b>	Multipurpose stage	<b>Condition</b>	ENCLOSED	Enclosed inside doors; three on stage, two in storage
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	B	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	12" pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	B	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	Floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	REMOVED	Removed
<b>Description</b>	6" pipe fitting insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District  
UTT INTERMEDIATE SCHOOL**

**TUSD  
171**

**Inspection Date: 4/5/2018**

<b>Building</b>	C	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Boiler room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Tank insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	12" pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	D	<b>Quantity</b>	1,000 LF	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by cove base
<b>Description</b>	Cove base mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Brown floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	12" pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**UTT INTERMEDIATE SCHOOL**

**TUSD**  
**171**

**Inspection Date: 4/5/2018**

<b>Building</b>	E	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	12" pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	G	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	G	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Beige floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Pipe insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b> N.A.
		<b>Hazard Ranking</b>		
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>UTT INTERMEDIATE SCHOOL</b>		<b>171</b>		
<b>Building</b>	H	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	K	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Throughout	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	9x9 Brown floor tile	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed except building A
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Roof	<b>Condition</b>	<b>REMOVED</b>	Removed Summer, 2005
<b>Description</b>	Patching mastic	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Under exterior windows	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>		N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.



**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**  
**UTT INTERMEDIATE SCHOOL**

**TUSD**  
**171**

**Inspection Date: 4/5/2018**

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	SURF	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

---

<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	
		<b>Hazard Ranking</b>	*	<b>Recommended Response Action</b>
		<b>Type</b>	MISC	Routine operations and maintenance
		<b>Friable Non-Friable</b>	NF	

David Johnson Certified Site Surveillance  
 Technician 17-5918

*Inspector Signature*

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>			<b>TUSD</b>	<b>Inspection Date: 4/5/2018</b>
<b>VEEH ELEMENTARY SCHOOL</b>			<b>17T</b>	
<b>Building</b>	A: Administration	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	277 SF	<b>Comments</b>
<b>Location</b>	Health office, workroom and storage	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	12x12 Beige floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	42 SF	<b>Comments</b>
<b>Location</b>	Health storage	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	A: Administration	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Teachers lounge heater closet	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct wrap	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	A: Administration	<b>Quantity</b>	3,500 SF	<b>Comments</b>
<b>Location</b>	Throughout except health office, workroom and storage	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Grey floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>VEEH ELEMENTARY SCHOOL</b>		<b>17T</b>		
<b>Building</b>	B: Kindergarten	<b>Quantity</b>	2,000 SF	<b>Comments</b>
<b>Location</b>	Kindergarten	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	HIGH	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Rooms 2-5	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhangs	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Rooms 2-5	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Food service	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	C: Rooms 2-5	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Food service	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	C: Rooms 2-5	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 2-5	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	D: Rooms 6-11	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**VEEH ELEMENTARY SCHOOL**

**17T**

<b>Building</b>	D: Rooms 6-11	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 6-11	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms 12-17	<b>Quantity</b>	7,500 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	E: Rooms 12-17	<b>Quantity</b>	5,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 12-17	<b>Condition</b>	<b>ENCLOSED</b>	Enclose by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Rooms 18-21	<b>Quantity</b>	1 EA	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>ENCLOSED</b>	No significant damage; enclosed in attic
<b>Description</b>	Transite flue pipe	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	F: Rooms 18-21	<b>Quantity</b>	2 EA	<b>Comments</b>
<b>Location</b>	Custodial office	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed inside doors; exposed in one door
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	Routine operations and maintenance
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	F: Rooms 18-21	<b>Quantity</b>	2,500 SF	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

**Tustin Unified School District**

**TUSD**

**Inspection Date: 4/5/2018**

**VEEH ELEMENTARY SCHOOL**

**17T**

<b>Building</b>	F: Rooms 18-21	<b>Quantity</b>	3,000 SF	<b>Comments</b>
<b>Location</b>	Rooms 18-21	<b>Condition</b>	<b>ENCLOSED</b>	Enclosed by carpet
<b>Description</b>	9x9 Tan floor tile	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	10,000 SF.	<b>Comments</b>
<b>Location</b>	Exterior walls and overhang	<b>Condition</b>	<b>GOOD</b>	No significant damage; <1% ACM
<b>Description</b>	Stucco	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	300 SF	<b>Comments</b>
<b>Location</b>	Exterior windows	<b>Condition</b>	<b>GOOD</b>	No significant damage
<b>Description</b>	Window putty	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	1	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Duct tape	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Furnace room	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Furnace gaskets	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.

"Verify ACM" = Possible asbestos-containing material not yet sampled.

**AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -**

<b>Tustin Unified School District</b>		<b>TUSD</b>		<b>Inspection Date: 4/5/2018</b>
<b>VEEH ELEMENTARY SCHOOL</b>		<b>17T</b>		
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Multipurpose ceiling beams	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Spray-applied fireproofing	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	H: Multipurpose	<b>Quantity</b>	2	<b>Comments</b>
<b>Location</b>	Northeast exterior doors	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Fire door insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	1	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Flex joints	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Heater rooms	<b>Condition</b>	<b>REMOVED</b>	Removed
<b>Description</b>	Aircell duct insulation	<b>Potential for Disturbance</b>	N.A.	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	TSI	
		<b>Friable Non-Friable</b>	F	
<b>Building</b>	Throughout	<b>Quantity</b>	834 SF	<b>Comments</b>
<b>Location</b>	Under windows	<b>Condition</b>	<b>GOOD</b>	No significant damage; one cracked panel at room 5
<b>Description</b>	Transite panels	<b>Potential for Disturbance</b>	MOD	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	Routine operations and maintenance
		<b>Type</b>	MISC	
		<b>Friable Non-Friable</b>	NF	
<b>Building</b>	Throughout	<b>Quantity</b>	N.A.	<b>Comments</b>
<b>Location</b>	Walkway roofs	<b>Condition</b>	<b>REMOVED</b>	Removed Summer 2011
<b>Description</b>	Patching mastic	<b>Potential for Disturbance</b>	LOW	<b>Recommended Response Action</b>
		<b>Hazard Ranking</b>	*	N.A.
		<b>Type</b>	SURF	
		<b>Friable Non-Friable</b>	NF	

\* Hazard Ranking is a function of condition and potential for disturbance (1=lowest, 7=highest). Applies only to friable materials.  
 "Verify ACM" = Possible asbestos-containing material not yet sampled.

***AHERA: SIX-MONTH SURVEILLANCE OF ASBESTOS-CONTAINING MATERIALS -***

---

**Tustin Unified School District  
VEEH ELEMENTARY SCHOOL**

**TUSD  
17T**

**Inspection Date: 4/5/2018**

---

**David Johnson Certified Site Surveillance  
Technician 17-5918**

---

***Inspector Signature***

